

ST. JOHN'S TWO DEPARTURE (VECTOR)

ST. JOHN'S INTL


ST. JOHN'S INTL, NF, CANADA

[UASF] AL-SL-1136

Rwy	Knots	60	120	180	240
20	V/V(fpm)	270	540	810	1080

Minimum Climb Rate To 900

ATIS 128.0 293.8
GND CON
121.9 275.8
ST. JOHN'S TOWER
120.6 236.6
GANDER CENTER
133.15 227.3



DEPARTURE ROUTE DESCRIPTION

TAKE-OFF ALL RWY: 1. Climb rwy hdg for vectors.

2. Maintain 5000 or as assigned.

COMMUNICATIONS FAILURE - TRANSPONDER MODE A/3 CODE 7600

On recognition of communications failure 10 minutes or less after take-off and in IFR weather conditions proceed as follows:

1. Upon reaching last assigned altitude proceed directly on course;

2. Maintain last assigned altitude for 10 minutes after take-off; then

3. Climb to flight planned altitude, except in the case of Trans Atlantic departures, climb to the altitude specified in the Oceanic Clearance.

Note: If communication failure occurs more than 10 minutes after take-off, comply with the appropriate procedure for communications failure enroute.

ST. JOHN'S TWO DEPARTURE (VECTOR)
(CYYT)

ST. JOHN'S INTL, NF, CANADA

ST. JOHN'S INTL

Effective 3 AUG 2006 - 31 AUG 2006