TACAN to ILS RWY 24

LOC MR	APCH CRS	Rwy ldg	9141
110.1	238°	TDZE	75
		Arpt Elev	75

[USAF] AL-2099 (RAF)

MARHAM (EGYM)

* When ALS inop, increase vis CAT AB to 1200m, CAT CDE to 1600m.

MISSED APPROACH: Climb on track 238° to 1580, then as directed.

ATIS *	MARHAM APP CON	MARHAM TOWER *	GND CON	PAR
277.225	124.15 233.075	122.1x 281.15	389.4	

CAUTION:
High risk of bird strike.

Subject to appropriate visual references achieved at DH, ILS suitable for auto coupled approaches to threshold.

RADAR REQUIRED







HIRL Rwy 06-24
LIRL Rwy 01-19

CATEGORY	A	B	C	D	E
S-ILS 24 *	280-800m 205 (300-800m)				
S-LOC 24	NOT AUTHORIZED				
CIRCLING	NOT AUTHORIZED				
S-PAR 24 *	280-800m 205 (300-800m) GS 3.00°				

FAF to MAP 4.5 NM

Knots	60	90	120	150	180
Min:Sec	4:30	3:00	2:15	1:48	1:30

Effective 3 AUG 2006 - 31 AUG 2006