



## DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RWY 14: Climb runway heading to 5000. At LQ 1.6 DME, but not less than 500 ft above DER, turn right....

AGARI 2B:....make a track of 180°. At LQ 4 DME turn left to make a track of 045°. Intercept GZO R-093 to AGARI.

GODAK 2B:....make a track of 180°. At LQ 4 DME turn left to make a track of 090°. Intercept MLT bearing 101° inbound to GODAK.

GZO 3B:....make a track of 235°. At GZO R-145 turn right to intercept the GZO R-155 inbound to GZO VOR. Cross GZO R-145 at or above 2500.

LORED 2B:....make a track of 180°. At LQ 4 DME turn left to make a track of 360°. Intercept GZO R-067 inbound to LORED.

OBITA 2B:....make a track of 235°. At GZO R-145 turn right to make a track of 275°. Intercept GZO R-246 inbound to OBITA. Cross GZO R-145 at or above 2500.

SUDIK 2B:....make a track of 200°. Intercept GZO R-161 inbound to SUDIK.