



TA 4000

DEPARTURE ROUTE DESCRIPTION

TAKE-OFF RWY 09: Climb to 3000 on heading 086°, thence...

Initial clearance limit FL60

PABSA 1T: Turn left heading 280° to intercept LNZ VOR/DME R-319 to PABSA. Cross LNZ 17 DME at or above 5000.

SBG 2T: Turn left inbound to LNZ VOR/DME. Proceed on LNZ R-267 and intercept SBG R-067 inbound to SBG VOR/DME. Cross LNZ 14 DME at or above 5000.

SUBEN 1T: Turn left heading 270° to intercept LNZ VOR/DME R-290 to SUBEN. Cross LNZ 17 DME at or above 5000.